
Assembly & Installation Instructions: Conform Accessory Flat Extension Arm CONF-ACC-1EXT-S



Parts Included



Required Parts Sold Separately

Selected Pole Mount option with mounting hardware Selected Conform Static Arms.

Tools Required

A Phillips head screwdriver, 2.5 mm Allen Wrench, 5 mm Allen Wrench




Do not use on hollow core tables.


Do not rotate or suspend arm beyond table surface.

If 3 arms are mounted in series, the maximum monitor weight in the entire system must not exceed 27 lb.

Do not link more than 3 arms in series.

NOTE: Extension cables for monitor power and video may be required.






Attach the Flat Extension Arm.

а

Remove M8 x 65 mm Bolt and Washers from Flat Extension Arm (A) as shown.

Attach the Flat Extension Arm continued.

Place the Arm on Pin. Assemble the Bolt and Washers as shown. Tighten with 5 mm Allen Wrench (included with base). Be sure the arm is tight but rotates freely. Snap on the Pivot Cover Cap. Tighten the installed set screw with a 2.5 mm Allen Wrench (included with base).





If 3 arms are mounted in series, the maximum monitor weight in the entire system must not exceed 27 lb. Do not link more than 3 arms in series.

4 of 4